

April 10, 2023

Project No.: 20234746.001A

Mr. Karl Kranz The Maryland Zoo in Baltimore 1876 Mansion House Drive Baltimore, MD 21217 p: 443.552.3350

c: 717.825.0948

Subject: Marsh Aviary Boardwalk – Structural Condition Assessment

Dear Mr. Kranz:

At your request, on March 22, 2023, Century Engineering, LLC (CE) performed a condition assessment of the existing Boardwalk, located in the Marsh Aviary Exhibit of the Maryland Zoo in Baltimore, MD. The purpose of our visit was to visually observe the physical condition of existing structural elements of the boardwalk. Our professional services were performed in accordance with our proposal dated December 20, 2022.

DESCRIPTION

The Marsh Aviary Boardwalk is located within the aviary exhibit, looping around the man-made waterways (Photo 1). The boardwalk consists of 2x10 PT beams spaced at 20", spanning between (2)3x10 + (2)2x10 (side members) built-up PT wood girders spaced up to 8'-0"±. The wood girders bear on concrete pier foundations, the girders are attached to the piers with bent steel plate connections. The 6x6 PT handrail posts typically are located at each end of the built-up wood girders. The handrail posts extend down between the two side 2x10 members of the built-up girder and are through bolted, the (2)3x10 members stop short, abutting the posts. The fencing consists of rope mesh strewn between steel bars that are attached to the wood rails / posts.

OBSERVATIONS

Due to limited access from waterways, enclosed areas and/or height restrictions of accessible areas, the entirety of the boardwalk framing could not be observed.

Construction drawings prepared by CLR Design were used for reference. See attached for marked-up plans indicating specific observations of handrail / framing deficiencies.

The following findings / deficiencies were observed:

- 1. 2x composite decking appears to be in good condition (Photo 2).
- Overall handrail is weathered, but solid. The top rail is covered with a continuous piece of composite material that is buckling in several locations (Photo 3).
- 3. There are several handrail posts that are deteriorated, with up to 100% section loss (Photo 4). These locations are noted on the attached plans.
- 4. There are several areas with deteriorated joists. White fungus was observed on the sides of several joists. These locations are noted on the attached plans (Photo 5).

- 5. There are several locations where the outer, side 2x10 members of the built-up wood girders are rotted with up to 100% section loss (Photo 6-7). These locations are noted on the attached plans. Typically the interior (2)3x10 members appear to be in good condition.
- 6. Jambs that support hinges for steel framed gates exhibit damage and, per staff's accounts, have to continually be adjusted. Due to excessive weight of the gates, the attachment points of the hinges are damaged, causing the gates to sag and become out of plumb (Photo 8).
- 7. Joist hangers appear to be in good condition overall.
- 8. Heavy steel connections appear to be in good condition.
- 9. Concrete piers appear to be in good condition.

RECOMMENDATIONS

There are several areas of concern with the handrail posts and boardwalk framing. A more indepth investigation is recommended. This will require that the composite decking be removed, in order to expose questionable framing members. Further deterioration may be discovered once the questionable are is exposed.

CE recommends the following:

- 1. Replace buckled composite handrail topping. Consider leaving gaps for expansion per manufacturer's recommendations.
- 2. Handrail posts with section loss shall be removed and replaced with 6x6 PT posts, reattach handrail.
- 3. Deteriorated joists shall be removed and replaced with 2x10 PT joists.
- 4. 2x10 girder side members that are deteriorated shall be removed and replaced with new 2x10 members. Joist and handrail post connections will need to be reinstalled. Joist connecters will likely need to be replaced.
- 5. Heavy steel connections will have to be reconnected where side members of girders are to be replaced. Interior 3x10 members will need to be observed once exterior, deteriorated 2x10 members are removed.

Thank you for the opportunity to perform these services for you. Please contact us if you have any questions or if we can be of service to you in any way.

Sincerely,

CENTURY ENGINEERING, LLC, A KLEINFELDER COMPANY

Gary W. Swift Senior Engineer

Building Structures Division

Gregory S. Holland Vice President

Building Structures Division



Professional Certification. I hereby certify that these documents were prepared or approved by me, and that I am a duly licensed professional engineer under the laws of the State of Maryland License No. 32548, Expiration Date 06-22-2024



Photo 1 – Exhibit photo




Photo 2 – Composite decking

CENTURY ENGINEERING, LLC, A KLEINFELDER COMPANY10710 Gilroy Road, Hunt Valley, MD 21031 p | 443.589.2400 f | 443.589.2401



Photo 3 – Buckled composite railing topping material



Photo 4 – Deterioration of 6x6 PT handrail post at base connection

CENTURY ENGINEERING, LLC, A KLEINFELDER COMPANY10710 Gilroy Road, Hunt Valley, MD 21031 p | 443.589.2400 f | 443.589.2401



Photo 5 – Mold observed on the sides of rotted 2x10 joists





Photo 6 – Rotted 2x10 side members of built-up wood girder



Photo 7 – Rotted 2x10 side members of built-up wood girder w/embedded ice pick





Photo 8 – Damaged jambs at gate connections



PIER NO.	AREA	DIAMETER	DEPTH BELOW FINISH GRADE	DETAIL	TOP OF PIER ELEVATION	REMARKS
NO. 1	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	REWARNS
<u> </u>	Interior Aviary Boardwalk		4' depth			
2	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	243.70	
3	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	243.30	
4	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	242.99	
5	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	242.68	
6	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	242.38	
7	•	24" dia.		5/ST-702	242.38	
8	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	242.38	
9	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	242.38	
10	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	242.23	
11	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	242.07	
12	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.91	
13	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.64	
14	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.37	
15	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.10	
16	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.10	
17	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.10	
18	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.10	
19	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.10	
20	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.10	
21	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.10	
22	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.10	
23	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.10	
24	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.20	
25	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.30	
26	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.62	
27	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.93	
28	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	242.25	
 29	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	242.56	
30	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	242.91	
31	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	243.26	
32	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	243.61	
33	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	243.86	
34	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
35	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
36	West Vestibule	18" dia.	4' depth	3/ST-420	244.10	
30 37	West Vestibule West Vestibule	18" dia.	4' depth	3/ST-420	244.10	
3 <i>1</i> 38	West Vestibule West Vestibule	18" dia.	4' depth	3/ST-420	244.10	
36 39	West Vestibule West Vestibule	18" dia.	4' depth	3/ST-420	244.10	
			4' depth	 		
40	West Vestibule	18" dia.	4 depth 4' depth	3/ST-420	244.10	
41	West Vestibule	18" dia.	· · · · · · · · · · · · · · · · · · ·	3/ST-420	244.10	
42	East Vestibule	18" dia.	4' depth	3/ST-420	244.10	
43	East Vestibule	18" dia.	4' depth	3/ST-420	244.10	
44	East Vestibule	18" dia.	4' depth	3/ST-420	244.10	
45	East Vestibule	18" dia.	4' depth	3/ST-420	244.10	
46	East Vestibule	18" dia.	4' depth	3/ST-420	244.10	
47	East Vestibule	18" dia.	4' depth	3/ST-420	244.10	
48	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
49	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
50	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
51	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
52	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
53	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
54	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
55	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
 56	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
57	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
58	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
59	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
60	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
61	Exterior Aviary Boardwalk	24 dia. 24" dia.	4' depth	5/ST-702	244.10	
62	Exterior Aviary Boardwalk	24 dia. 24" dia.	4' depth	5/ST-702	244.10	
62 63	Exterior Aviary Boardwalk		4' depth			
	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
64	•	24" dia.		5/ST-702	244.10	
65	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
66	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
67	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
68	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
69	Int Brdwalk Keeper Stairs	18" dia.	4' depth	7/ST-702	242.00	
	-		•		ı	1
70	Int Brdwalk Keeper Stairs	18" dia.	4' depth	7/ST-702	242.00	

See ST-410 for exhibit grading information.







IN BALTIMORE

Marsh Aviary Renovation



ARCHITECTURE LANDSCAPE ARCHITECTURE EXHIBIT DESIGN

833 chestnut street, suite 1000 philadelphia, pa 19107
DESIGN t 215. 564. 0250 f 215. 564. 1154

CENTURY ENGINEERING CONSULTING ENGINEERS — PLANNERS

10710 GILROY ROAD

HUNT VALLEY, MD 21031

Phone: (443) 589-2400 **Fa**x: (443) 589-2401



Project Management

10720 Beaver Dam Road, 2nd Floor Baltimore, Maryland 21030 Phone: 410.771.1701 Fax: 410.771.1702

Revisions	Date
Schematic Design Drawings	11.30.2012
95% CD Set	03.01.2013

Boardwalk Layout Plan North

Sheet Title


Project No.: 10013 Project Manager: JS

Checked: MB Drawn: MF

Scale: As Noted


Date: 03.01.2013


Drawing No.




PIER NO.	AREA	DIAMETER	DEPTH BELOW FINISH GRADE	DETAIL	TOP OF PIER ELEVATION	REMARKS
1	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
2	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	243.70	
3	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	243.30	
4	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	242.99	
5	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	242.68	
6	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	242.38	
7	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	242.38	
8	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	242.38	
9	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	242.38	
10	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	242.23	
11	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	242.07	
12	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.91	
13	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.64	
14	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.37	
15	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.10	
16	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.10	
17	Interior Aviany Boardwalk	24" dia.	4' depth	5/ST-702	241.10	
18	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.10	
19	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.10	
20	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.10	
21	Interior Aviary Boardwalk Interior Aviary Boardwalk	24" dia.	4' depth 4' depth	5/ST-702	241.10	
22	Interior Aviary Boardwalk Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.10	
23	Interior Aviary Boardwalk Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.10	
24	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	241.20	
25 26	Interior Aviary Boardwalk	24" dia. 24" dia.	4 depth 4' depth	5/ST-702 5/ST-702	241.30 241.62	
	Interior Aviary Boardwalk		4' depth			
27 28	Interior Aviary Boardwalk	24" dia. 24" dia.	4' depth	5/ST-702 5/ST-702	241.93	
<u>20</u> 29	Interior Aviary Boardwalk	24 dia. 24" dia.	4' depth	5/ST-702	242.25 242.56	
30	Interior Aviary Boardwalk	24 dia. 24" dia.	4' depth	5/ST-702	242.90	
31	Interior Aviary Boardwalk	24 dia. 24" dia.	4' depth	5/ST-702	243.26	
32	Interior Aviary Boardwalk	24 dia. 24" dia.	4' depth	5/ST-702	243.20	
33	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	243.86	
34	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
35	Interior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
36	West Vestibule	18" dia.	4' depth	3/ST-420	244.10	
37	West Vestibule	18" dia.	4' depth	3/ST-420	244.10	
38	West Vestibule	18" dia.	4' depth	3/ST-420	244.10	
39	West Vestibule	18" dia.	4' depth	3/ST-420	244.10	
40	West Vestibule	18" dia.	4' depth	3/ST-420	244.10	
41	West Vestibule	18" dia.	4' depth	3/ST-420	244.10	
42	East Vestibule	18" dia.	4' depth	3/ST-420	244.10	
43	East Vestibule	18" dia.	4' depth	3/ST-420	244.10	
44	East Vestibule	18" dia.	4' depth	3/ST-420	244.10	
45	East Vestibule	18" dia.	4' depth	3/ST-420	244.10	
46	East Vestibule	18" dia.	4' depth	3/ST-420	244.10	
47	East Vestibule	18" dia.	4' depth	3/ST-420	244.10	
48	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
49	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
50	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
51	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
52	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
53	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
54	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
55	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
56	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
57	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
58	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
59	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
60	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
61	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
62	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
63	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
64	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
65	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
66	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
67	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
68	Exterior Aviary Boardwalk	24" dia.	4' depth	5/ST-702	244.10	
69	Int Brdwalk Keeper Stairs	18" dia.	4' depth	7/ST-702	242.00	
70	Int Brdwalk Keeper Stairs	18" dia.	4' depth	7/ST-702	242.00	
71	Boardwalk Keeper Stairs	18" dia.	4' depth	7/ST-702	242.00	I

Notes:
See ST-410 for exhibit grading information.







Marsh Aviary Renovation



ARCHITECTURE LANDSCAPE ARCHITECTURE EXHIBIT DESIGN

833 chestnut street, suite 1000 philadelphia, pa 19107
DESIGN t 215. 564. 0250 f 215. 564. 1154

CENTURY
ENGINEERING
CONSULTING ENGINEERS - PLANNERS
10710 GILROY ROAD
HUNT VALLEY, MD 21031

HUNT VALLEY, MD 21031
Phone: (443) 589-2400 Fax: (443) 589-2401



HDC, Inc.Project Management

10720 Beaver Dam Road, 2nd Floor Baltimore, Maryland 21030 Phone: 410.771.1701 Fax: 410.771.1702

Seal:

Revisions	Date
Schematic Design Drawings	11.30.2012
95% CD Set	03.01.2013

Boardwalk Layout Plan North

Sheet Title


Project No.: 10013

Project Manager: JS

Drawn: MF Checked: MB

Scale: As Noted

Date: 03.01.2013





Marsh Aviary Renovation

ARCHITECTURE LANDSCAPE ARCHITECTURE EXHIBIT DESIGN

833 chestnut street, suite 1000 philadelphia, pa 19107
DESIGN t 215. 564. 0250 f 215. 564. 1154

CENTURY ENGINEERING

CONSULTING ENGINEERS — PLANNERS

10710 GILROY ROAD

HUNT VALLEY, MD 21031


Phone: (443) 589-2400 Fax: (443) 589-2401

HDC, Inc. Project Management 10720 Beaver Dam Road, 2nd Floor Baltimore, Maryland 21030 Phone: 410.771.1701

Date Schematic Design Drawings 11.30.2012 03.01.2013

Boardwalk Layout Plan South

Project Manager: JS





Marsh Aviary Renovation

ARCHITECTURE LANDSCAPE ARCHITECTURE EXHIBIT DESIGN

833 chestnut street, suite 1000 philadelphia, pa 19107 D E S I G N t 215. 564. 0250 f 215. 564. 1154

HUNT VALLEY, MD 21031

> HDC, Inc. Project Management

10720 Beaver Dam Road, 2nd Floor Baltimore, Maryland 21030 Phone: 410.771.1701 Fax: 410.771.1702

Date Schematic Design Drawings 11.30.2012 03.01.2013

Boardwalk Layout Plan South